

Fig. 2




Fig. 3




Fig. 5




Fig. 4




Fig. 8




Fig. 9




Fig. 6




Fig. 7




Fig. 10

```
graph TD; A[PROVIDE CURABLE ADHESIVE] --> B[PROVIDE INDEXING MEANS]; B --> C[PROVIDE APPLICATION MEANS]; C --> D[PROVIDE SOURCE OF DIES]; D --> E[PROVIDE ATTACHING MEANS]; E --> F[PROVIDE CONTROL MEANS]; F --> G[OPERATE CONTROL MEANS TO CAUSE ADHESIVE TO BE APPLIED TO EACH LEAD FRAME AND TO ATTACH EACH DIE TO A LEAD FRAME];
```

PROVIDE CURABLE ADHESIVE

PROVIDE INDEXING MEANS

PROVIDE APPLICATION MEANS

PROVIDE SOURCE OF DIES

PROVIDE ATTACHING MEANS

PROVIDE CONTROL MEANS

OPERATE CONTROL MEANS TO CAUSE ADHESIVE TO BE APPLIED TO EACH LEAD FRAME AND TO ATTACH EACH DIE TO A LEAD FRAME

Fig. 11